

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
Company	Dan Guy				
OGM	Pete Hess				

Inspection Report

Permit Number:	C0070016
Inspection Type:	PARTIAL
Inspection Date:	Thursday, August 26, 2010
Start Date/Time:	8/26/2010 9:30:00 AM
End Date/Time:	8/26/2010 11:40:00 AM
Last Inspection:	Wednesday, July 21, 2010

Inspector: Pete Hess.

Weather: Sunny and hot; mid 80's F. InspectionID Report Number: 2466

> Accepted by: dhaddock 9/15/2010

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY

Site: GORDON CREEK 2, 7 & 8 MINES

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	179.27
Total Disturbed	34.15
Phase I	32.52
Phase II	32.52
Phase III	0.73

Mineral Ownership

Types of Operations ✓ Underground **✓** Federal State ☐ Surface ☐ Loadout County Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Gordon Creek 2 / 7 / 8 site has received several thunderstorm events since the July inspection.

Inspector's Signature:

Pete Hess,

Inspector ID Number: 46

Date

Thursday, Aug



Permit Number: C0070016 Inspection Type: PARTIAL

Inspection Date: Thursday, August 26, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V		✓	
4.d	Hydrologic Balance: Water Monitoring	~		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V		V	
10.	Slides and Other Damage		V		
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	V		V	
13.	Revegetation	✓		✓	
14.	Subsidence Control		V		
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing		~		
16.b	Roads: Drainage Controls		V		
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check				
20.	Air Quality Permit		✓		
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070016 Inspection Type: PARTIAL

Inspection Date: Thursday, August 26, 2010

Page 3 of 3

2. Signs and Markers

The Permittee identification sign is not located at the intersection of the permit boundary and the Carbon County road; it appears to have been stolen since the July 21, 2010 inspection. Mr. Guy will replace the sign.

4.a Hydrologic Balance: Diversions

Undisturbed runoff from the County road located north of the disturbed area (at the ridge line) is reporting onto the mine site through the first reclamation diversion. Most of the sediment reporting onto the mine site was stopped by the last stand of quaking aspen at the east disturbed perimeter. The flow cut the upper layer of sediment, which lies on channel riprap. The riprap was not eroded through. Mr. Guy indicated that several layers of riprap actually exist in the channel. The County road located atop the east ridge has had its berm breeched in two locations. The Permittee will have the berm repaired by either the County Road Department or some other means.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The reclaimed sediment pond area is flourishing with vegetation. The water level in Jacob's Pond is about 1.5 feet below the discharge elevation of the open channel spillway. The contained water is very turbid.

4.c Hydrologic Balance: Other Sediment Control Measures

The sites upper reclamation channels show indication that flow has reported through them to the main channel. Much of the vegetation within the channels is laid over.

4.d Hydrologic Balance: Water Monitoring

There was no flow observed in Bryner Creek this day. Mr. Guy estimated that Jacob's Pond contains 18 to 24 inches of water.

9. Protection of Fish, Wildlife and Related Environmental Issues

An elk carcass was seen inside the mine site reclamation area. This was reported to Mr. Bill Bates at the Price DWR.

12. Backfilling And Grading

All backfilled areas at the site remain stable.

13. Revegetation

The County has received several events over the summer; vegetation at the site appears to be doing very well.